Work	Orde	r ID	70461
WOLK	virue	T 117	/ ()/4() [

Page 1

Thursday, June 09, 2011 7:40:59 AM

Item ID:

D3535-21

Accept

Setup Start

Stop

Stop



Revision ID:

Start Date:

Item Name: Wearshoe

Required Date: 6/13/2011

6/9/2011

Start Otv: 6.00 Rea'd Otv: 6.00

**Cust Item ID: Customer:** 

Reference:

Approvals:

**Process Plan:** 

Date: //-//-9

Tooling:

Date:

Date:

Start Run



OC:

Operation

Date:

SPC (Y/N):

Tool # Plan Accept Reject

Reject

Insp.

**Draw Nbr** 

Sequence ID/

Work Center ID Description Revision Nbr

Set Up/ **Run Hours**  Tool ID

Code Oty

Oty

Number

Stamp

D3535

Rev B

100

Waterjet

FLOW WATER JET

Memo

Deburr if necessary

1-Cut as per Dwg D3535 □Dwg Rev: 0.00

0.00

□Prog Rev: \ \ □2-

1811-6-10

FLOW CNC Wateriet

"304. G40

QC2- Inspect parts off machine FAl/FAIB

0.00

Memo

0.00

B11-6-10

Quality Control

120

QC

110

QC8- Inspect parts - second check

D W06/13

Memo

Quality Control

### Work Order ID 70461

Thursday, June 09, 2011 7:40:59 AM



Page 2

Item ID:

D3535-21

Accept



Setup Start



**Revision ID:** 

**Start Date:** 

Item Name:

**Required Date: 6/13/2011** 

Wearshoe

6/9/2011

Start Qty: 6.00

Req'd Qty: 6.00

Stop

Stop

Reference:

Approvals:

Process Plan:

**Operation** 

**Description** 

Date: \_\_\_\_\_

**Tooling:** 

Date: Date: Run Start

Date: \_\_\_\_\_

SPC (Y/N):

Set Up/

**Run Hours** 

**Tool ID** 

**Cust Item ID:** 

**Customer:** 

Tool # Plan

Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

130

Sequence ID/

**Work Center ID** 

Brake NC Brake NC

NC BRAKE

0.00

0.00

Form bend & joggle as per Dwg D3535 using DT8261 & DT8326

140

Quality Control

QC5- Inspect part completeness to step on W/O

150

Powdercoat

Powder Coating

M115128

Grey Sandtex(Ref:4.3.5.6) per OSI005 4.3

Memo

0.00

Memo

6x 8 M/1/06/14

### Work Order ID 70461

Thursday, June 09, 2011 7:40:59 AM



Page 3

Item ID:

D3535-21

Accept

Setup Start

Stop



**Revision ID:** 

Start Date:

Item Name:

Wearshoe

6/9/2011

Start Oty: 6.00

Req'd Otv: 6.00

**Cust Item ID:** 

**Customer:** 

**Tool ID** 

Reference:

Approvals:

Required Date: 6/13/2011

Process Plan:

Date:

Date: \_\_\_\_

Tooling:

SPC (Y/N):

Date:

Date:

Tool # Plan

Code

Run Start

Reject



QC:

Sequence ID/ Work Center ID

160

Quality Control

Operation Description

QC3- Inspect Part Finish

Set Up/ **Run Hours** 

0.00

Memo

0.00

Accept

Qty/

Qty

Stop

Reject Insp. Number Stamp

170

Packaging

Packaging

Identify as per dwg & Stock Location

Memo

Memo

0.00

180

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

## **Picklist Print**

Thursday, June 09, 2011 7:40:57 AM

Work Order ID: 70461

Parent Item: D3535-21

Parent Item Name: Wearshoe



Start Date: 6/9/2011

Required Date: 6/13/2011

Start Qty: 6.00

Required Oty: 6.00

Comments:

IPP Rev:A New Issue 07-02-15 JLM

IPP Rev:B As per Rev B 07-08-31 JLM

Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S20GA		Purchased	No	0.00		100	sf	249.9814	0.8925	5.636842			
										KB(11-	-6-10		

304/316 .040 Sheet

Location	Loc Oty	Loc Code	
MAT020	249.9814		
116623	0.2		
117550	10.1814		-
117933	239.6		17933

Page 1

DART AEROSPACE LTD	Work Order:	70461
Description: Wearshoe	Part Number:	D3535-21
Inspection Dwg: D3535 Rev: B		Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.188	+0.005/-0.001	(19)	_		V 1862	
2.000	+/-0.010	2.606	4		V	
2.000	+/-0.010	2.000	15		ν	
1.885	+/-0.010	1.888	9		V	<u> </u>
0.300	+/-0.010	.34	7		V	
0.300	+/-0.010	,366	<b>-</b>		V (	
5.450	+/-0.010	5.456	4		7 4801	
10.900	+/-0.010	10,900	<b>Y</b>		7	
16.350	+/-0.010	16.35	V		7	
21.800	+/-0.010	21.800	<b>-</b>		7	
27.250	+/-0.010	27-750	7		τ	
32.700	+/-0.010	1	<u>د</u>		T	
6.00	+/-0.030	6,00	6		7	
8.00	+/-0.030	8,00	~		7	
16.00	+/-0.030	16.00	Э		7	
24.00	+/-0.030	24.00	٤		7	
0.040	+/-0.010	,036	8	***************************************	V	

Measured by:	Audited by: 8	Prototype Approval:	N/A
Date: 11-6-16	Date: 11/04/13	Date:	N/A

Rev	Date	Change		pproved
Α	10.2.02	New Issue	KJ 96	XX

Dart A	Aerospace	Ltd
--------	-----------	-----

<b>-</b> a	Jopase	Liu								
W/O:				٧	ORK ORDER CHANGES					
DATE	STEP	PRO	CEDUR	E CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							. 1			
									·	
Part No	•	PAR #:	Fau	t Ca	tegory: NC	R: Yes	No <b>DQ</b>	A:	_ Date: _	
	R	esolution:	Disp	osit	ion: Q <i>i</i>	A: N/C (	Closed:		Date: _	
NCR:		V	VORK	OR	DER NON-CONFORMANC	E (NC	R)			
DATE	STEP	Description of NC			Corrective Action Section B		Verific	cation	· Approval	Approval
DAIL	J.L.	Section A	Init Chief		Action Description Chief Eng	Sign Dat		ion C	Chief Eng	QC Inspector

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE


## **Dart Aerospace Ltd**

Dail AC	ospace	s Llu								
W/O:			WO	RK ORDER CH	ANGES	· · · · · · · · · · · · · · · · · · ·				
DATE	STEP	PRO	OCEDURE CHAN	NGE		Ву	Date Q	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	r	NCR: Yes	No DQA:_		_ Date: _	
	R	esolution:	Disposition	):	<u> </u>	A: N/C Clo	sed:		_ Date: _	
NCR:			WORK ORDE	R NON-CONFO	RMAN	CE (NCR)	)			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Action Descrip	Section E	Sign &	Verification		Approval	Approval
		Section A	Chief Eng	Chief Eng		Date	Section C	_	Chief Eng	QC Inspector
					:					

NOTE: Date & initial all entries



DESIGN	DRAWN BY	DART	AEROSPACE USA, INC.
CHECKED	APPROVED/	DRAWING NO.	REV. B
4		D3535	SHEET 7 OF 7
DATE	4	TITLE	SCALE
07.04.17		WEARSHOE	1:1



Copyright © 2006 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Dail Aci				ļ						
W/O:				WORK ORDER CHANGES						
DATE	STEP	PROCEDUR			IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No: PAR #:			Fau	_ Fault Category: NC _ Disposition: QA			R: Yes No DQA: Date:			
			Dis				\: N/C Closed:			·
NCR:			WORK	OR	DER NON-CONFORMANC	E (NC	R)			
DATE	STEP	Description of NC Section A	Init	Corrective Action Section B Initial Action Description				cation	Approval	Approval
				Eng	Action Description Chief Eng	Sign Date		Section C	Chief Eng	QC Inspector
		2.2								

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE